



DeLorme Publishing, Inc.
Two DeLorme Drive
Yarmouth, ME 04096

GPS2058-10 Module Firmware Release Notes

Firmware Version: 1.1.0

Issue Date: April 3, 2008

Product ID (Description):

GPS2058-10 (DeLorme ordering code GM-205810-000)

Description of Changes:

- 1) Corrected UART baud rate error affecting 19.2K baud rates and higher
- 2) Enabled six GPIO module pins and the commands to control them

All other features remain unaffected for backwards compatibility.

For Additional Information:	Contact Information
Product Manager	Brian Stearns 207-846-7111 x2383 brian.stearns@delorme.com
Hardware Engineering Director	James Zeigler
Quality Assurance	Kurt Boutin